

Product Safety Recall



Carbatec AF-2000C Room Air filter

Sold from September 2017 to March 2019

Defect: Machine possibly not earthed correctly:

Caused by a new thicker powder coating process between component panels of the machine.

Hazard: Electrical Hazard due to possible lack of earth on some components.

What to Do: Please contact Carbatec to coordinate the repair of your machine. All owners have now been contacted.

Carba-Tec New Zealand Limited:

Email: orders@carbatec.co.nz

Phone: 09 274 9454

Website: www.carbatec.co.nz

See www.recalls.govt.nz for
other New Zealand consumer product recalls