

Product Safety Recall



CarbaTec RT-660 Router Table

RT-660 Router Tables

Sold nationwide between July 2012 and October 2016

Defect: In the switch unit attached to the leg there have been some instances where the Phase and Neutral wires have been swapped to the output socket.

Hazard: Wiring does not comply with New Zealand standards. Could be hazardous if used for purposes other than those it is intended for.

What to do: Please disconnect the Router Table from the power supply and contact CarbaTec NZ who will arrange for the switch to be couriered to Auckland for checking and repairing (if necessary).

Contact details: For more details please call;

phone: 0800 444 329

email: admin@carbatec.co.nz

online: www.carbatec.co.nz

New Zealand Importer/Distributor

Carba-Tec New Zealand limited

110 Harris Road, East Tamaki, Auckland 2013

New Zealand

0800 444 329

See www.recalls.govt.nz for
other New Zealand consumer product recalls